Aircraft Cleanability and Corrosion Issues



26 February 2008

Craig Matzdorf NAVAIR



maintaining the data needed, and c including suggestions for reducing	lection of information is estimated to ompleting and reviewing the collecti this burden, to Washington Headqu uld be aware that notwithstanding an DMB control number.	ion of information. Send comments arters Services, Directorate for Infor	regarding this burden estimate of mation Operations and Reports	or any other aspect of the 1215 Jefferson Davis	is collection of information, Highway, Suite 1204, Arlington	
1. REPORT DATE 26 FEB 2008	2 DEPORT TYPE			3. DATES COVERED 00-00-2008 to 00-00-2008		
4. TITLE AND SUBTITLE				5a. CONTRACT NUMBER		
Aircraft Cleanabili	5b. GRANT NUMBER					
				5c. PROGRAM ELEMENT NUMBER		
6. AUTHOR(S)				5d. PROJECT NUMBER		
				5e. TASK NUMBER		
				5f. WORK UNIT NUMBER		
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Naval Air Warfare Center, Materials Engineering Division, 22347 Cedar Point Road, Patuxent River, MD, 20670 8. PERFORMING ORGANIZATION REPORT NUMBER						
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)		
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)		
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited						
13. SUPPLEMENTARY NOTES Surface Finishing and Repair Issues for Sustaining New Military Aircraft Workshop, February 26-28, 2008, Tempe, AZ. Sponsored by SERDP/ESTCP.						
14. ABSTRACT						
15. SUBJECT TERMS						
16. SECURITY CLASSIFIC	17. LIMITATION OF	18. NUMBER	19a. NAME OF			
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified	Same as Report (SAR)	OF PAGES 13	RESPONSIBLE PERSON	

Report Documentation Page

Form Approved OMB No. 0704-0188

Outline



- Overview of M&P Linked to "Cleanability"
- Overview of M&P Linked to Corrosion Issues
- Efforts Underway
- M&P Technology Gaps for Sustaining Aircraft

M&P Needs Linked to Cleanability



Cleanability drives:

- Cosmetic painting and weight gain
- Additional corrosion maintenance, reduced lifetime

Materials & Processes

- Topcoats: weathering, gloss & gloss retention, cleanability- as painted and after weathering or corrosion exposure
- Semi-aqueous cleaners- AF and NAVAIR spec products
- Cleanability Test- Used in topcoat and cleaner specs
- Wash Pads
- Wash and Rinse Intervals
- Basing: geographic location, sheltering

M&P Needs Linked to Corrosion



- Mildew removal
- Chemical paint remover, field use
- Paints
 - Self-Priming Topcoat
 - Unauthorized aerosol paints
 - Primers & Topcoats
- Improved Corrosion Preventive Compounds
 - Navguard
 - MIL-L-87177
 - Fluid Film CID
- Pre-coated Fasteners- Fred Lancaster brief tomorrow
- Boot and Tape removal
- Conversion Coating Touch Up Pens
- Improved -85570 Type II Cleaners
- Repair of new coatings




Geographic Assessment







Comparison of Corrosion Rate Data for Navy Sites to Worldwide Distribution: 1-Year Cumulative Corrosion of 6061-T6 Aluminum



Navy/Marine Aviation and Air Force Land Sites



Carrier Exposure Rack on CVN 74



(Abbott and Kinzie, 2004)

Naval Aviation Sheltering

NAVMAIR

EA-6B shelters at Whidbey Island, WA




Funding: OSD Corrosion IPT and DLA Reliability Program

- Purchase and install shelters at Whidbey Island and Oceana (EOY 2006)
- Monitor performance of aircraft under shelters compared to control aircraft
- Install corrosivity sensors under shelter and next to shelter, collect data and compare results to aircraft



T-45 shelters at NAS Meridian

- Evaluation of impact on aircraft corrosion (and other maintenance) planned for 2006-2008:
 - EA-6B at NAS Whidbey, WA
 - T-45 at NAS Kingsville & NAS Meridian
 - F/A-18 at NAS Oceana, VA
- Assess aircraft performance compared to sensor data
- EA-18G at Whidbey NAS- potential implementation during airfield upgrade



Sheltering showing up to 5-fold reduction in corrosivity in carrier environment and similar attenuation at Tyndall AFB, FL

Corrosion-Inhibited Mildew Remover





- Joint NAVAIR & AMCOM assessment of reformulated Mildew Remover
 - Meets critical characteristics specified in MIL-PRF-85570 and ADS-61A-PRF cleaning specs
 - Effectively removes mildew without corrosion risk of bleach
- U.S. Patent applications filed for compositions & kit
- Composition and kit licensed to commercial supplier
- NAVAIR & AMCOM authorized in 2005
- Implementation pending FIFRA registration and NSN assignment













Paints



- Topcoats (MIL-PRF-85285)
 - CSG assessing properties of current topcoats with intent to upgrade overall topcoat requirement in spec or create new type for "APC" or "ELT" products with clearly defined performance requirements

• Primers

- Current non-chromate products being field tested
- Details in my talk tomorrow
- Unauthorized Aerosol paints: 2-prong attack to eliminate use
 - 2K products now authorized and being used (MIL-PRF-85285 and MIL-PRF-23377 products)
 - 1K products being assessed (MIL-PRF-81352)
 - Type I and Type III

Improved CPCs



- MIL-PRF-81309
 - Long-lived Internally-Applied Corrosion Preventive Compound ("Navguard")
 - Multi-year F/A-18 Field Test underway
 - Product Licensed to Industry
 - Commercial products being tested against requirements to MIL-PRF-81309 (Armick & Corrosion Technologies)
- MIL-L-87177
 - Raytheon test report delivered to NAVAIR
 - Decision on implementation pending
- Fluid Film
 - Commercial Item Description being developed by NAVAIR



Tape and Adhesive Remover



- Objective- Demonstrate & validate 3M TAR (Tape and Adhesive) Remover
- Problem- Mechanical removal of radome neoprene boots, polyurethane belly and leading edge tapes causes significant substrate damage often these protective materials are not re-applied as a result
- 2008 Plans- Dem/val of TAR product in field for squadron use, finalize testing and authorization

Type II Touch Up Pen



- Objective- Field test new MIL-PRF-81706 Type II products in applicator pen format
- Problem- NAVAIR has implemented Type II, nonchromate surface preparation for use under chromated primers. Two Type II touch up pen products are commercially available but have not been assessed
- 2008 Plans- Dem/val, qualify and implement (if successful) the Type II pens for "lead the fleet" use at FRC Cherry Point

RTU MIL-PRF-85570 Cleaner



- Objective- Assess and Implement Improved "RTU" or aerosol cleaners
- Problem- Current MIL-PRF-85570 Type I or II Low cleaning efficiency often high-pH deck cleaners used on A/C as well (shipboard)
- 2008 Plans- Review current "Sudsie Bubbles" use shipboard on A/C 85570 Type I aerosol Investigate OTS products to test against existing FRC cleaners/solvents

Technology Gaps for Sustaining Aircraft



Chemical Paint Stripper- peroxide activated products not good enough

 Need: Product that removes qualified primers and topcoats in field, at low temperatures, ~40 F, similar strip rates to methylene chloride

• Semi-Aqueous Aircraft Cleaners- not very good at cleaning aircraft soils, shelf-life stability issues

 Need: More effective Type II (NAVAIR) and Type IV (AF) cleaners with improved shelf-life stability

Primers

- Need: Non-chromate primers with equivalent performance to chromated primers
- Need: Water-reducible primers with similar barrier properties to solventborne primers

Topcoats

 Need: products with improved weathering, gloss retention, and corrosion performance with qualified primers (C and NC, solvent and water)